

JOHN A. WILSON,
Civil Engineer.
JOS. M. WILSON,
Civil Engineer & Archt.
FRED. G. THORN,
Architect.
HENRY W. WILSON,
Civil Engineer.
CHARLES G. DARRACH,
Civil & Hydraulic Engineer.
HENRY A. MACOMB,
Architect.

Wilson Brothers & Co.

Civil Engineers and Architects.

No. 435 Chestnut St.
Philadelphia, Pa. Aug. 4th, 1887.

Hon. Daniel M. Fox,

Supt., U. S. Mint,

Philadelphia.

Dear Sir:

I would respectfully call your attention to the fact that your employees in the rolling room and in the melting room, throw out a great deal of rubbish upon the roof of the new boiler house. This rubbish and dirt not only makes the place unsightly, but it has a tendency to collect around the inlet to rain water drain, and prevents the rain water from flowing off from the roof as it should do. The consequence is, that the water flows over the cornice and disfigures the marble.

Very respectfully,

Charles S. Darnell
per W. H. Darnell

NARA RG104, Entry 1, Box 147

Wilson Brothers & Co.
Civil Engineers and Architects,
Philadelphia, Pa.
August 4, 1887

Hon. Daniel M. Fox,
Supt., U.S. Mint,
Philadelphia.

Dear Sir:

I would respectfully call your attention to the fact that your employees in the rolling room and in the melting room, throw out a great deal of rubbish upon the roof of the new boiler house. This rubbish and dirt not only makes the place unsightly, but it has a tendency to collect around the inlet to rain water drain, and prevents the rain water from flowing off from the roof as it should do. The consequence is, that the water flows over the cornice and disfigures the marble.

Very respectfully,
Chas. G. Darrach
per W. Bro. Co.